Oil Field Environmental Incident Summary

Incident: 20150902103205 Date/Time of Notice: 09/02/2015 10:32 Responsible Party: ENERPLUS RESOURCES USA CORPORATION **ENERPLUS RESOURCES USA CORPORATION** Well Operator: Well Name: NEEDLE 149-93-05AH Field Name: MANDAREE Well File #: 22727 Date Incident: 9/1/2015 Time Incident: 17:00 Facility ID Number: County: DUNN **Twp:** 149 **Rng:** 93 **Sec:** 5

Location Description:

Submitted By: Shannon Oliver Received By:

Contact Person: Josh Ruffo

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Equipment Failure

Release Contained in Dike Yes - Within Dike Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil 2 Barrels 2 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No immediate risk from incident.

Areal Extent:

Completely contained within steel dike containment.

Potential Environmental Impacts:

No environmental impacts from incident; completely contained within dike.

Action Taken or Planned:

Valve repaired and re-seated. Oil was cleaned up with a vac truck and contaminated soil will be removed.

Wastes Disposal Location: Recovered oil was put back in the system and the contaminated soil will

be sent to an approved landfill.

Agencies Involved:

Updates

Date: 9/2/2015 Status: Reviewed; BIA/Tribal Lead Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.